Level 6 Lined Vest

Materials Needed: Fabric, Interfacing & Lining.

- 1. Choose fabric & lining. (Remember, if using a stripe or plaid, to match them up.)
- 2. Layout pattern & cut fabric, lining & interfacing. Mark the circles.
- 3. Trim 1/4" off of interfacing around entire edge of front piece. Fuse to wrong side of each front piece.
- 4. Stay stitch 3/8" of fabric and lining at arm holes and back neck edge.
- 5. Sew fabric front to fabric back at shoulders, right sides together, matching notches, using a 5/8" seam. Repeat for lining. Press seams open.
- 6. Pin lining to vest, right sides together, matching notches, centers and shoulder seams. Turn back 5/8" of lining side seam. Sew 5/8" seam around arm holes starting and stopping at marked circles. Sew 5/8" seam around lower edge and neck edge.
- 7. Grade, clip & notch seams. Press.
- 8. Turn right side out. (It is suggested that you under-stitch wherever you can. Under-stitching is done inside between the fabric and lining, by stitching the seam allowance to the lining. On the top side of the lining, the lining appears to be top stitched.)
- 9. Sew side seams of fabric at 5/8". Press.
- 10. Turn under the lining and slip stitch the lining side seam. Press.







